



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

RCVD OCT 8 '13
OIL CONS. DIV.
DIST. 3

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10-8-2013 Operator COPC API # 30-0 39-07655

Property Name San Juan 29-7 Unit Well # 57 Location: Unit L Sec 11 Twn 29 Rge 7

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒ _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): Yes TA Expires: 10-8-2018

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 0
Int. Casing Pres. 0

Pressured annulus up to 570 psi. for 31 mins. Test passed/~~failed~~

REMARKS: Pressure dropped to 565, but held steady last 11 min.

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

Site Supervisor
(Position)

Revised 02-11-02