

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report


Name of Company: ConocoPhillips Company	Contact Lisa Hunter
Address 3401 E. 30th Street, Farmington, NM 87402	Telephone No. 505-326-9786
Facility Name Jicarilla 20 #9	Facility Type Oil Well
Surface Owner Jicarilla Tribe	Mineral Owner Jicarilla Tribe
API No. 300-39-22745 Jicarilla Contract: 64	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	20	25N	04W	600'	North	430'	West	Rio Arriba

Latitude 36.39069 Longitude -107.28222

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered 2 bbls
Source of Release Pit Tank overflowed	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery 09-16-2013 @ 1:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bryce Hammond, Jicarilla EPA Brandon Powell, NMOCD	
By Whom? Lisa Hunter	Date and Hour 09-17-13 Bryce Hammond @ 8:43 a.m. by phone and email follow up Brandon Powell @ 8:50 a.m. - Courtesy Call	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. RCVD SEP 20 '13	
If a Watercourse was Impacted, Describe Fully.* N/A	OIL CONS. DIV. DIST. 3	
Describe Cause of Problem and Remedial Action Taken.* Pit Tank overflowed causing a release of 10 bbls of Produced Water, of which 2 bbls were recovered. Fluids were contained. Well was shut in and water truck recovered free standing fluid. Third-part Environmental will assess impacted area for further remediation.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will install level pit/tank shut downs will be installed and well will be more closely monitored. Will assess the soils to determine further action, if needed.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa M. Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 10/23/2013	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: September 19, 2013	Phone: 505-326-9786	

* Attach Additional Sheets If Necessary

NSK1329652447