



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OCT 25 2013

Date of Test 8/13/13 Operator Elm Ridge Exploration CO LLC API #30-039-05188

Property Name Jicarilla A 156 Well No. 001 Location: Unit A Section 1 Township 23N Range 02W

Well Status(Shut-In or Producing) Initial PSI: Tubing 29 Intermediate 0 Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>30</u>		
10 min	<u>0</u>		<u>30</u>		
15 min	<u>0</u>		<u>30</u>		
20 min	<u>0</u>		<u>30</u>		
25 min	<u>0</u>		<u>30</u>		
30 min	<u>0</u>		<u>30</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing ☒	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By Frank Welch
pumper
(Position)

Witness _____

E-mail address _____