



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

AUG 20 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-8-13 Operator _____ API #30-0 3930504

Property Name NEBU Well No. 22M Location: Unit 0 Section 36 Township 36 Range 7W

Well Status(Shut-In or Producing) Initial PSI: Tubing 37 Intermediate 182 Casing 58 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	182	58	0	58
10 min	0	182	58	0	58
15 min	0	182	58	0	58
20 min	0	182	58	0	58
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

INTERM BLEW DEAD WITHIN 2 MINUTES
NO PRESSURE BUZZ

By DAN MULLIGAN
LEASE OPERATOR
(Position)

Witness Anthony Pacheco

E-mail address _____

