



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/IN3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

AUG 15 2013

(submit 1 copy to above address)

Date of Test 8/9/2013 Operator Western Minerals and Oil API #30-0 39-82334
Property Name Hurt Well No. 1 Location: Unit E Section 11 Township 25N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 56 Intermediate — Casing 60 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
5 min						
10 min						
15 min						
20 min						
25 min						
30 min						

Steady Flow

Surges

Down to Nothing

X 4 seconds

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE —

REMARKS:

Blew down in 4 seconds to nothing.
No liquids

By Bob Chensault
Lease Operator
(Position)

Witness —

E-mail address bob@ccinm.com