



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3/district.htm](http://emnr.state.nm.us/ocd/District%20III3/district.htm)

OIL CONS. DIV DIST. 3

AUG 15 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/8/2013 Operator Western Minerals and Oil API #30-0 45-21835
Property Name Marron Well No. 60A Location: Unit C Section 24 Township 21N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 96 Intermediate - Casing 132 Bradenhead 21

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	<u>⊖</u>				<u>132</u>
10 min	<u>⊖</u>				<u>132</u>
15 min	<u>⊖</u>				<u>132</u>
20 min	<u>⊖</u>				<u>132</u>
25 min	<u>⊖</u>				<u>133</u>
30 min	<u>⊖</u>				<u>133</u>

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X 18 seconds</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD ⊖

INTERMEDIATE _____

REMARKS:

Blew down right away and never
built back up. No liquids

By Bobi Chenault
Lease Operator
(Position)

Witness _____

E-mail address bob@ccnm.com