



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD MAY 29 '13

OIL CONS. DIV.
DIST. 3

Date of Test 5/29/2013 Operator ConocoPhillips API #30-0 39-23223

Property Name San Juan 30-5 Unit Well No. 103 Location: Unit M Section 3 Township 30 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing 148 Intermediate 27 Casing 148 Bradenhead 27

OPEN-BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	2	151	0	159
10 min	0	2	153	0	160
15 min	0	1.8	155	0	162
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	X
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0.3

INTERMEDIATE 0

REMARKS:

Through 1" fittings. Bradenhead down to a whisper in 1:30 min, down to nothing in 2:30 min.
blew some debris @ initial, blew down in 5 sec after 5 min shut-in. Intermediate blew down
in 1 sec.

By Pat Stawinski core msd
(Position)

Witness James D. Kelly

E-mail address _____