District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-144 June 1, 2004

For drilling and production facilities, submit to appropriate NMOCD District Office.

For downstream facilities, submit to Santa Fe

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes \boxtimes No \square Type of action: Registration of a pit or below-grade tank \square Closure of a pit or below-grade tank \boxtimes

	ephone: (505) 326-9841 e-mail a	ddress: <u>LHasely@br-in</u>	c.com			
Address: 3401 East 30th Street, Farmington, New Mexico, 87402 Facility or well name: Pinon Mesa A2EAPI	#: <u>30045263890000</u> U/L or Qtr/Qtr <u>E</u> Sec	36 T 031N R 0	14W			
County: San Juan Latitude N36 51.584 Longitude W108 15.986 NAD: 1927 \ 1983 \ \[\]						
Surface Owner: Federal □ State □ Private □ Indian ⊠						
<u>Pit</u>	Below-grade tank	W	•			
Type: Drilling Production Disposal	Volume: 60 bl Type of fluid: Produced Construction material: Fiberglass	Water and Incidental Oil				
Workover □ Emergency □ Lined □ Unlined □	Double-walled, with leak detection? Yes If It is a superior of the superior is a superior in the superior in	not explain why not				
Liner type: Synthetic Thicknessmil Clay	No – Tank was installed prior to Rule 50.	. 1101, 011p1				
Pit Volumebbl						
Depth to ground water (vertical distance from bottom of pit to	Less than 50 feet	(20 points)				
seasonal high water elevation of ground water.)	50 feet or more, but less than 100 feet 100 feet or more	(10 points) (0 points)	20			
	100 feet of more	(o points)	20			
Wellhead protection area: (Less than 200 feet from a private	Yes	(20 points)				
domestic water source, or less than 1000 feet from all other	No	(0 points)	0			
water sources.)						
Distance to surface water: (horizontal distance to all wetlands,	Less than 200 feet	(20 points)				
playas, irrigation canals, ditches, and perennial and ephemeral	200 feet or more, but less than 1000 feet	(10 points)				
watercourses.)	1000 feet or more	(0 points)	10			
	Ranking Score (Total Points)		30			
			30			
If this is a pit closure: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if your are burying in place) onsite \Box offsite \Box If offsite, name of facility (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No \boxtimes Yes \Box If yes, show depth below ground surfaceft. and attack sample posters.						
(5) Attach soil sample results and a diagram of sample locations and excavations.						
Additional Comments:		TO THE PARTY OF TH				
Pit Location – 60 feet ,90 degrees from the wellhead. Soil sample collected 3 feet below bottom of tank. Soils tested clean and no soil remediation was required. Lab analysis attached. Distriction – 60 feet ,90 degrees from the wellhead. Constitution – 60 feet ,90 degrees from the wellhead. Distriction – 60 feet ,90 degrees from the wellhead.						
Soil sample collected 3 feet below bottom of tank. Soils tested clean and no soil remediation was required. Lab analysis attached.						
Soil sample collected 3 feet below bottom of tank. Soils tested clean and no soil remediation was required. Lab analysis attached.						
/		<u> </u>				
	The Control of the Co	······································	322 - 11/2			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or complete to the below-grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □, or an (attached) alternative described approved plan □.						
Date: 10/ 02/05	100,1					
Date: 10/02/05 Printed Name/Title Ed Hasely, Environmental Advisor Signature 2 Hasely						
Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate						
ground water or otherwise endanger public health or environment. Nor does it relieve the operator of its responsibility for compliance with any other						
federal, state, or local laws and/or regulations.						
Approval: DEPUTY OIL & GAS INSPECTOR, DIST. BU Signature Date Date Date						
and are as are a constitue, but a far	1 emy ker	OCT	0 6 2005			



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	Burlington Resources	Project #:	92115-001-14133
Sample ID:	Pinon Mesa A2E	Date Reported:	08-05-05
Laboratory Number:	33935	Date Sampled:	07-27-05
Chain of Custody No:	14133	Date Received:	08-01-05
Sample Matrix:	Soil	Date Extracted:	08-02-05
Preservative:	Cool	Date Analyzed:	08-05-05
Condition:	Cool and Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	8.0	0.2
Diesel Range (C10 - C28)	3.4	0.1
Total Petroleum Hydrocarbons	11.4	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

BG Tank (Area 4).

DID=25.1

Ahalyst Coping

Muster Maeters
(Review