



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-12-14 Operator Domunion API #30-0 31-20118
Property Name South Hospital Well No. 36 Location: Unit 6 Section 12 Township 17 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 60 Intermediate VA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Bradenhead Int	Csg	INTERM Int	Csg	
TIME						
5 min	<u>0</u>		<u>0</u>			
10 min	<u>0</u>		<u>0</u>			
15 min	<u>0</u>		<u>0</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		<u>DIST. 3</u>
Surges		<u>OIL CONS. DIV.</u>
Down to Nothing		
Nothing	<u>/</u>	
Gas		<u>RCVD FEB 12 '14</u>
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE VA

REMARKS:

Well has no sign - needs M.T. Producing
Injection - nothing when opened
No picture - Cannot pump

By Rafael Corp

Witness Monica Kuehling

(Position)

E-mail address _____