

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Lindsay Dumas
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 599-4089
Facility Name: Zachry 14	Facility Type: Gas
Surface Owner BLM	Mineral Owner BLM (SF-080724A)
API No. 3004513067	

LOCATION OF RELEASE

Unit Letter M	Section 10	Township 28N	Range 10W	Feet from the 1100'	North/South Line South	Feet from the 1170'	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	---------------------------

Latitude 36.67236 Longitude -107.88746

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 BBLS	Volume Recovered 3 BBLS
Source of Release Pit tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 2/26/14 12:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*	RCVD MAR 7 '14 OIL CONS. DIV. DIST. 3	
Describe Cause of Problem and Remedial Action Taken.* Pit tank began leaking due to corrosion. Well was shut in and fluid was pulled. Pit will be replaced and soil will be sampled under liner.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 3/11/2014	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval: Lab analysis and chlorides samples required	Attached <input type="checkbox"/>
Date: 3/5/14	Phone: (505) 599-4089	

* Attach Additional Sheets If Necessary

nJK1407025206