



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-17-14 Operator L. W. Energy API #30-0 39-07947
Property Name NEBU Well No. 11 Location: Unit H Section 25 Township 31 Range 7
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 42 Intermediate Casing 67 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		65		
10 min	0		67		
15 min	0		69		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	DIST 3
Gas	
Gas & Water	OIL CONS DIV.
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

RCVD MAR 17 '14

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 1/1

REMARKS:

BH closed at 18 seconds - Med Blow

By [Signature]

Witness

[Signature]

(Position)

E-mail address