



RCVD MAR 27 '14  
OIL CONS. DIV.

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

DIST. 3

Date of Test 3-27-14 Operator Bayless API #30-0 45-30688

Property Name Harold Boland (10) Well No. 2 Location: Unit \_\_\_ Section 10 Township 30 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 64 Intermediate N/A Casing 65 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		67		
10 min	0		67		
15 min	0		65		
20 min					
25 min					
30 min					

**FLOW CHARACTERISTICS**

**BRADENHEAD INTERMEDIATE**

Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	✓
Gas & Water	
Water	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_ FRESH \_\_\_ SALTY \_\_\_ SULFUR \_\_\_ BLACK \_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Light blow to dead at 8 seconds.

By Brendy Aranda  
Pumper  
(Position)

Witness Monica Treking

E-mail address \_\_\_\_\_