

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Florance GC J 16	Facility Type: Natural Gas Well Location

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004509800
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter: A	Section: 6	Township: 30N	Range: 09W	Feet from the 1010	North/South Line North	Feet from the 990	East/West Line East	County: San Juan
-------------------	---------------	------------------	---------------	-----------------------	---------------------------	----------------------	------------------------	------------------

Latitude 36.84507 Longitude 107.81637

NATURE OF RELEASE

Type of Release: unknown hydrocarbon	Volume of Release: unknown	Volume Recovered: none
Source of Release: 21 bbl BGT	Date and Hour of Occurrence: unknown - historical in nature	Date and Hour of Discovery: 3/10/2014
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

RCVD MAR 24 '14
OIL CONS. DIV.
DIST. 3

Describe Cause of Problem and Remedial Action Taken.*
During the closure of a 21 BGT on location impacted soil was encountered below the base of the BGT. A sample was collected and sent for laboratory analysis. Laboratory analysis returned results above the standards set forth in the NMAC for TPH. Laboratory analysis documentation included with this report.

Describe Area Affected and Cleanup Action Taken.*
Further investigation will be needed to determine depth and extent of impacts.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Environmental Advisor	Approval Date: 4-17-14	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/20/2014 Phone: 505-326-9457		

* Attach Additional Sheets If Necessary

Incident # NCS 1410755727