



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emr.d.state.nm.us/ocd/District III/3district.htm](http://emr.d.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

**BRADENHEAD TEST REPORT**

APR 11 2014

(submit 1 copy to above address)

Date of Test 4-4-14 Operator Four STAR oil-gas API #30-0 45-08938

Property Name nm com Well No. 0-1 Location: Unit N Section 36 Township 30 Range 10

Well Status (Shut-In or Producing) Initial PSI: Tubing 32 Intermediate X Casing 30 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min	0		32		
10 min	0		35		
15 min	0		37		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing <u>X 6 sec</u>		
Nothing		
Gas		
Gas & Water		
Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

Blew dead in 6 sec

By Randy Caldar

Witness \_\_\_\_\_

Caldar service  
(Position)

E-mail address Randy.C@caldar-service.com