

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report



Name of Company Burlington Resources Oil & Gas Company	Contact Lindsay Dumas	
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 599-4089	
Facility Name: Largo Federal 1A	Facility Type: Gas	
Surface Owner Federal	Mineral Owner BLM (NM-0555563)	API No. 3004523562

LOCATION OF RELEASE

Unit Letter C	Section 34	Township 29N	Range 9W	Feet from the 1190	North/South Line FNL	Feet from the 1595	East/West Line FWL	County San Juan
-------------------------	----------------------	------------------------	--------------------	------------------------------	--------------------------------	------------------------------	------------------------------	---------------------------

Latitude **36.686220** Longitude **-107.771880**

NATURE OF RELEASE

Type of Release Hydrocarbon	Volume of Release 64 BBL	Volume Recovered 27 BBL
Source of Release Oil/Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 2/10/14 1130 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell, Jonathon Kelly & Shari Ketcham	
By Whom? Lindsay Dumas	Date and Hour 2/10/14 @ 3:45 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. RCVD FEB 19 '14	
If a Watercourse was Impacted, Describe Fully.* OIL CONS. DIV. DIST. 3		
Describe Cause of Problem and Remedial Action Taken.* Two holes were found 8" from bottom of tank, oil leaked into ground towards pit. Some oil settled in bottom of water pit containment and this was recovered.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 4/28/14	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/10/14 Phone: (505) 599-4089		

* Attach Additional Sheets If Necessary

NCS 1411841877