



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

APR 30 2014

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 30 APR 2014 Operator BURL WARD API #30-0 025 29
Property Name SJ 29-7 Well No. 29 Location: Unit 29 Section 29 Township 29 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 136 Intermediate 0 Casing 138 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead	INTERM	Int	Csg
TIME		Int	Csg		
5 min		0	139		140
10 min		0	139		140
15 min		8	140		140
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing			
Nothing	X		X
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

OPENED THE BRADEN HEAD AND NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND NOTHING CAME OUT.

By Alvin Hamed

Witness [Signature]

(Position)

E-mail address _____