



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-30-14 Operator WPK Energy API #30-0 43-21147
Property Name Chaco 22 06 28 Well No. 22814 Location: Unit Section 2 Township 22 Range 6
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 76 Intermediate 0 Casing 74 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	73	0	72
10 min	0	0	73	0	72
15 min	0	0	71	0	71
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	✓
Gas & Water	✓
Water	

DIST. 3

OIL CONS. DIV.

ROUND APR 30 '14

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH. nothing when opened.
Int. light puff when opened.

By Lady Boyd
LEAD Field Tech
(Position)

Witness Monica Gutierrez

E-mail address