



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrpd.state.nm.us/ocd/District III3district.htm](http://emrpd.state.nm.us/ocd/District%20III3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 09 2014

Date of Test 04/29/14 Operator Thompson Engineering API #30-0 45-28489

Property Name Jones 35L Well No 10 Location: Unit C Section 35 Township 29N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 6 Intermediate NA Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>30</u>		
10 min	<u>0</u>		<u>30</u>		
15 min	<u>0</u>		<u>30</u>		
20 min	<u>0</u>		<u>30</u>		
25 min	<u>0</u>		<u>30</u>		
30 min	<u>0</u>		<u>30</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

opened the valve and nothing blew out. had to
dig up valve.

By Theo Hampton

Witness

(Position)

E-mail address