



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

RCVD MAY 7 '14
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-MAY-2014 Operator COLEMAN API #30-0 45-29633
Property Name MIDDLE MESA COM Well No. 3 Location: Unit M Section 33 Township 32 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 3 Bradenhead 102

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min			6		
10 min			8		
15 min			9		
20 min			10		
25 min			10		
30 min			10		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas		
Gas & Water	X	
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK X

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT PRODUCED APPROXIMATELY
10 GALLONS OF WATER IN THE FIRST 5 MINUTES AND STOPPED PRODUCING
WATER AT 8 MINUTES AND BLEW DOWN TO NOTHING IN 10 MINUTES

By Bill Royce
Lease Operator
(Position)

Witness John Durham

REQUESTED A
WATER ANALYSIS

E-mail address _____