



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1680 RIO BRAZOS ROAD
AZTEC NIA 87410
(505) 334-6178 FAX: (505) 334-6170
<http://landfill.nrd.state.nm.us/ocod/District1/HD3District1.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/17/14 Operator El Paso API # 30-045-30752
Property Name McDaniel Well No. 1 Location: Unit _____ Section 30 Township 29N Range 10W
Well Status (Shut-In or Producing) Initial PSI: Tubing 2 Intermediate N/A Casing 12 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	N/A	12		
10 min	1	1	12		
15 min			12	N/A	
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		N/A
Nothing	X	
Gas		
Gas & Water		
Water		

OIL CONS. DIV DIST. 3

MAY 07 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

3 MINUTE SHUT-IN PRESSURE BRADENHEAD X INTERMEDIATE N/A

REMARKS:

no fluids

By E. L. G.

Witness _____

(Position)

E-mail address _____