



(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

90-0682

(submit 1 copy to above address)

cc
John B.
John A.
John C.

Well Status(Shut-In or Producing) Initial PSI: Tubing 123 Intermediate 89 Casing 124 Bradenhead 152

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD ↗

INTERMEDIATE 22

REMARKS:

REMARKS: OPENED THE BRADENTHEAD AND IT PARULLED DOWN
D NOTHING IN 5 SECONDS. OPENED THE INTERMEDIATE AND
IT PARULLED FOR THE ENTIRE 30 MINUTES. REQUESTED A GAS ANALYSIS
AND GAS STREAM

By Gregory D. Dale

Witness John B. Brown

(Position)

E-mail address _____