



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-21-14 Operator Maralex Resources API #30-0 45-29/93
Property Name Cecil Cast Well No. #1 Location: Unit Section 19 Township 30N Range 11W
Well Status (Shut-In or Producing) Initial PSI: Tubing 2# Intermediate N/A Casing 2# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0	N/A	2#	N/A	N/A
10 min	0		2#		
15 min	0		2#		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
MAY 27 2014

If bradenhead flowed water, check all of the descriptions that apply below:

N/A

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

By [Signature]
Pumper
(Position)

Witness _____

E-mail address _____