

MEW MIEXICO EMERGY, MIMERAILS & NATURAL RIESOURCES IDEPARTMIENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District Ill/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-39-14 Operator	XTO ENLIGY API	#30-045-30742
Date of Test 5-39-14 Operator XTO ENLIGY API #30-0 45-30742 Property Name Galver Well No. 6A Location: Unit Section 25 Township 32 Range 9		
Well Status(Shut-In or Producing) Initial PSI: Tubing 45 Intermediate O Casing D Bradenhead		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH		
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CH BRADENHEAD	ARACTERISTICS INTERMEDIATE
TIME 0 0 50 0 50	Steady Flow	
10 min 0 0 50 0 50	Surges	
15 min 0 0 50 0 50	Down to Nothing /	Vict 5
20 min	Nothing	OH COME DIVI
25 min	Gas	7575 MAY 2011 4
30 min	Gas & Water	
	Water	
If bradenhead flowed water, check all of the descriptions that apply below:		
CLEAR FRESH SALTY SULFUR BLACK		
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE		
REMARKS: BH- July Whelle Devect.		
Int light blowto dead at 27 Decencls.		
By July Roden Witness / Wille Cull Cull		
Lense opter		
(Position) E-mail address		
E-man address	•	