



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/10/2014 Operator COPC API #30-0 39-30582

Property Name San Juan 29-7 Well No. 73C Location: Unit C Section 24 Township 29 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 130 Intermediate 76 Casing 131 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	76	131	0	133
10 min	0	76	133	0	133
15 min	0	76	133	0	133
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Just a whisper on bradenhead. Intermediate blew down
in 19 seconds

RCVD JUN 10 '14

DIST. 3

By [Signature]
COP
(Position)

Witness Paul Wiebe

E-mail address _____