



OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/oed/District III3district.htm](http://emnrd.state.nm.us/oed/District%20III3district.htm)

SHOT IN
7:30 9-JUNE-2014

(submit 1 copy to above address)

Date of Test 10-JUNE-2014 Operator CONOCO API #30-0 YS 11344

Property Name Bar 16A 32-7 Well No. 11 Location: Unit _____ Section 20 Township 32 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 141 Intermediate 140 Casing 145 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	1	142	147		150
10 min		143	148		151
15 min		145	149		152
20 min					152
25 min					152
30 min					153

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	X
Surges	
Down to Nothing	
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

[illegible]

CLEAR FRESH SALTY SULFUR BLACK

[illegible]

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE **6** **15**

REMARKS:

OPENED THE BRAZENHEAD AND NOTHING CAME OUT.

OPENED THE INTERMEDIATE AND IT HAD A LIGHT FLOW FOR THE ENTIRE TEST, REQUESTED A GAS ANALYSIS AND WAS STREAM

By 

Witness [Signature]

(Position)

E-mail address