



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/11/2014 Operator COPC API #30-0 45-34555

Property Name W M Hanley Well No. 2 F Location: Unit N Section 18 Township 29 Range 10

Well Status (~~Shut In~~ or Producing) Initial PSI: Tubing 171 Intermediate 0 Casing 123 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	173	0	123
10 min	0	0	173	0	173
15 min	0	0	173	0	123
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD JUN 11 '14

OIL CONS. DIV.

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE _____

DIST. 3

REMARKS:

Nothing on bradenhead. Intermediate blew down in
5 seconds

By Paul Sirb
MSO RUN 311
(Position)

Witness Paul Wike

E-mail address _____