



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/DistrictIII/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/11/14 Operator Cowdoo Phillips API #30-0 45.28549
Property Name S332.74 Well No. 301 Location: Unit Section 34 Township 32 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 1074 Intermediate 0 Casing 0 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>
10 min	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>
15 min	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>✓</u>	<u>✓</u>
Nothing	<u>✓</u>	<u>✓</u>
Gas	<u>✓</u>	<u>✓</u>
Gas & Water		
Water		

OIL CONS. DIV DIST. 3

JUN 20 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

BH ↓ to nothing in 2 sec.

Gas Analysis requested.

Int. ↓ to nothing in 2 min & 17 sec. !!!

By David Aguirre
SWD MBO
(Position)

Witness

Monica Kuehlins

E-mail address