



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-25-2014 Operator COPC API #30-0 45-29845

Property Name Cl Paso Well No. 1B Location: Unit E Section 20 Township 29 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 84 Intermediate — Casing 91 Bradenhead 12

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0	—	92		
10 min	0	—	93		
15 min	0	—	93		
20 min	0	—	94		
25 min	0	—	94		
30 min	0	—	94		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	✓
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	✓

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

RCVD JUN 25 '14

OIL CONS. DIV.

DIST. 3

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Spayed when opened down to surges, then down to nothing
in 6 min. Requested water sample.

By Mamgoharley MSO
Mamgoharley MSO 215
1180
(Position)

Witness Paul Wike

E-mail address —