NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/23/2014 Operator Burlington API #30-0 39-27333

Property Name San Juan 29-7 Unit Well No. 190 Location: Unit ___ Section 16 Township 29 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 116 Intermediate NA Casing 121 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Int	Csg	INTERM Int	Csg
TIME 5 min	1		123		
10 min	2.2		124		
15 min	2.2		124		
20 min	2.2		125		
25 min	2.2		125		
30 min	22		125		

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

OIL CONS. DIV DIST. 3

JUN 23 2014

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 2.5 INTERMEDIATE NA

REMARKS:
BHT ran through 1" valve for 1st 5 min then through 1/4" valve on gauge T for rest of test, did not blow down during test. Requested gas analysis from BH and production. Opened 1" for an additional 3 min, higher initial blow, then steady flow

By [signature] Witness Jonathan O. Kelly

MSO
(Position)

E-mail address _____