



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 7-8-14 Operator Energex Res. API # 30-0 39-24454

Property Name Quintana Mesa Com Well # 100 Location: Unit K Sec 28 Twn 32 Rge 5

Land Type:

State _____
Federal /
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation /

Temporarily Abandoned Well (Y/N): _____ TA Expires: 7-8-2019

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 1290
Int. Casing Pres. _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

OIL CONS. DIV DIST. 3

JUL 08 2014

Pressured annulus up to 570 psi. for 30 mins. Test passed/failed

REMARKS:

KP 3759
Perfs 3848-3904
dropped to 558- held last 10 minutes

By William Sandoz
(Operator Representative)

Witness Mona Kuehling
(NMOCD)

(Position)

Revised 02-11-02

60 0 30-039-244 54 5

55 EMERGEN

50

45

40

35

30

25

20

15

10

Graphic Controls

CHART NO. MC MP-1000-1HR
WEATHER OF Farmington

METER

CHART PUT ON M

LOCATION Quintana MESA com #100

REMARKS Line = 1 min

7-8-14

TAKEN OFF M

OIL CONS. DIV DIST. 3
JUL 08 2014