



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District II/3district.htm](http://emnrd.state.nm.us/ocd/District%20II/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 17 2014

Date of Test 3-20-14 Operator Energen Resources API #30-0 3924136

Property Name Jicarilla 107 Well No. 5A Location: Unit L Section 33 Township 26 Range 4

Well Status(Shut-In or Producing) Initial PSI: Tubing 152 Intermediate Casing 158 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		158		
10 min	0		161		
15 min	0		164		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

WELL JUST WENT TO OFF CYCLE ON THE CLOCK.

By MICHAEL L DEAN
PRODUCTION FOREMAN
(Position)

Witness

E-mail address