



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

APR 17 2014

Date of Test 3-19-14 Operator Energex Resources API #30-0 3924169

Property Name Camas unit FR 112 Well No. 12112 Location: Unit E Section 34 Township 32N Range 5W

Well Status (Shut-In or Producing) Initial PSI: Tubing 38 Intermediate N/A Casing 39 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>39</u>		
10 min	<u>0</u>	<u>N/A</u>	<u>39</u>		
15 min	<u>0</u>	<u>N/A</u>	<u>39</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

when opening bradenhead no blow no vapor no water

By Mk Hu

Witness Sam Moke

Mk Hu Lease operator
(Position)

E-mail address _____

OIL CONS. DIV DIST. 3

APR 17 2014