



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/28/2014 Operator CO-PC API #30-0 45-33566

Property Name Hare Well No. 14M Location: Unit D Section 10 Township 29 Range 10

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 58 Intermediate 12 Casing 84 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	12	81	8	84
10 min	0	12	79	6	85
15 min	0	12	81	4	86
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	☒
Surges	☐
Down to Nothing	☐
Nothing	☒
Gas	☒
Gas & Water	☐
Water	☐

RCVD JUL 28 '14

OIL CONS. DIV.

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 4

REMARKS:

Nothing on bradenhead. Intermediate, slight blow for the
15 min. test.

By Cherry J. J.
MSO
(Position)

Witness Paul Wiebe

E-mail address _____