



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/6/2014 Operator Burlington API #30-0 45-29998
Property Name Helms Federal Well No. 1B Location: Unit Section 22 Township 30 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 87 Intermediate 411 Casing 85 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	411	85	65	85
10 min	0	411	85	34	85
15 min	0	411	85	29	85
20 min				27	85
25 min				27	85
30 min				27	85

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	X
Down to Nothing	X
Nothing	
Gas	
Gas & Water	X
Water	

OIL CONS. DIV DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

AUG 06 2014

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 123

REMARKS:
BA through 1/4" needle valve, blew down to nothing in 20 sec. Intermediate
through 2" line to BBT, hard blow for 1 min 30 sec, moderate blow for
30 sec, then ~~moderate~~ flow w/ surges in fluid and gas for entire test.

By Roy CHANDLER
m30
(Position)

Witness Jonathan D. Kelly

E-mail address Roy.CHANDLER@CONCREPHILLIPS.COM