



# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-18-14 Operator Energizer API #30-0 39-30502  
Property Name McCroden Well No. 8B Location: Unit    Section 3 Township 25 Range 3  
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 56 Intermediate NA Casing 67 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>68</u>		
10 min	<u>0</u>		<u>68</u>		
15 min	<u>0</u>		<u>69</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	<u>DIST. 3</u>
Gas & Water	<u>OIL CONS. DIV.</u>
Water	<u>RCVD AUG 18'14</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR    FRESH    SALTY    SULFUR    BLACK   

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Nothing when opened. Extra spool 13 5/8-  
Drillation 9 5/8-  
this well is cleaned.

By MICHAEL C DEAN

Witness

Monica Cuchling

701 PRODUCTION FOREMAN

(Position)

E-mail address