



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 8-15-14 Operator Enurwest LP. API # 30-0 45-33583

Property Name Rio Bravo Well # 5 Location: Unit 7 Sec 27 Twn 31 Rge 13

Land Type:

State _____
Federal _____
Private /
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal /
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

SWD-1207-0 181-379

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. 650 Max. Inj. Pres. 31300
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 650
Int. Casing Pres. 11/11

Pressured annulus up to 450 psi. for 30 mins. Test passed/failed passed OIL CONS. DIV. AUG 15 '14

REMARKS:

Dacker out 3450

(op) Perf 3487

4286

By Chester Z. Osal
(Operator Representative)

Witness Monica Kuehling
(NMOCD)

(Position)

Revised 02-11-02

(505) 325-6173

GAS FROM EVEREST

STA NO.


LEASE RIO BRAVO #5 SWD SYSTEM

LEGAL
DESCR. SEC. 27-T31N-R13W GAS
TO

DATE 8/16/14 TIME OF TEST EFFECTIVE DATE 8/16/14

DIST. 3

OIL CONS. DIV.
RECD AUG 15 '14




Jade Sales & Service, Inc.

P.O. Box 2113

Wilmington, NM 87499

RECEIVED
AUG 11 2014
BY: _____



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1500

TAKEN OFF M

CHART PUT ON M

LOCATION

REMARKS

RIO BRUNO #5 SW21
8/6/2014

METER