



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/20/2014 Operator COPC API #30-0 45-35094

Property Name Ludwick LS Well No. 19P Location: Unit F Section 5 Township 29 Range 10

Well Status(~~Shut-In~~ or Producing) Initial PSI: Tubing 146 Intermediate 523 Casing 148 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0	523	148	0	148
10 min	0	523	148	0	148
15 min	0	523	148	0	148
20 min				0	148
25 min				0	148
30 min				0	148

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	RCVD AUG 20 '14
Gas & Water	OIL CONS. DIV.
Water	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Just a puff on bradenhead Intermediate blew down to
slight blow in 3 min. 30 sec. (2" pipe) Down to surges in 20 min.
Down to fumes in 25 min. Requested gas anal. and well bore sch.

By PAUL SIKORA
MJO Run 311
(Position)

Witness Paul Wreke

E-mail address _____