



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-8178 FAX: (505) 334-8170  
<http://emnrd.state.nm.us/ocd/DistrictIII3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-25-14 Operator Domunion API #30-0 31-20390

Property Name Santafe RCB Well No. 34 Location: Unit \_\_\_\_\_ Section 5 Township 17 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing \_\_\_\_\_ Intermediate VA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		DIST. 3
Down to Nothing		
Nothing	✓	OIL CONS. DIV.
Gas		RCVD JUL 25 '14
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE VA

REMARKS: Casing open - no tubing -

By Tom Crosby  
\_\_\_\_\_  
(Position)

Witness Monica Kuchler  
\_\_\_\_\_

E-mail address \_\_\_\_\_