



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/29/2014 Operator COPC API #30-0 45-11876

Property Name Rock Island Well No. 1 Location: Unit D Section 22 Township 29 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 199 Intermediate 0 Casing 355 Bradenhead 29

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	<u>1</u>	<u>0</u>	<u>356</u>	<u>0</u>	<u>357</u>
10 min	<u>1</u>	<u>0</u>	<u>356</u>	<u>0</u>	<u>358</u>
15 min	<u>1</u>	<u>0</u>	<u>356</u>	<u>0</u>	<u>358</u>
20 min	<u>1</u>	<u>0</u>	<u>356</u>		
25 min	<u>1</u>	<u>0</u>	<u>357</u>		
30 min	<u>1</u>	<u>0</u>	<u>357</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges	<u>OIL CONS. DIV DIST. 3</u>
Down to Nothing	<u>JUL 29 2014</u>
Nothing	
Gas	
Gas & Water	
Water <u>✓</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 20 INTERMEDIATE 0

REMARKS:

Bradenhead flowed 1/4 of a 1" pipe Nothing on Intermediate.
Requested water sample on bradenhead.

By _____

Witness Paul Wiebe

(Position)

E-mail address _____