



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/29/2014 Operator COPC API #30-0 45-21787

Property Name Koch State Corn Well No. 1A Location: Unit I Section 36 Township 29 Range 9

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 11 Intermediate - Casing 31 Bradenhead 68

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>1</u>	<u>-</u>	<u>31</u>		
10 min	<u>1</u>	<u>-</u>	<u>31</u>		
15 min	<u>1</u>	<u>-</u>	<u>31</u>		
20 min	<u>1</u>	<u>-</u>	<u>31</u>		
25 min	<u>1</u>	<u>-</u>	<u>31</u>		
30 min	<u>1</u>	<u>-</u>	<u>31</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges	OIL CONS. DIV DIST. 3
Down to Nothing	JUL 29 2014
Nothing	
Gas	
Gas & Water	
Water <u>✓</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 64 INTERMEDIATE _____

REMARKS:

Bradenhead had steady flow out 1" pipe. 5 minute
shut in 64 Requested water sample

By _____

Witness Paul Wike

(Position)

E-mail address _____