



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

RCVD AUG 22 '14

OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test 22 AUG-20 14 Operator ENTRGEN API #30-0 45-11434

Property Name SAN JUAN 32-S Well No. 18 Location: Unit B Section 16 Township 32 Range S

Well Status(Shut-In or Producing) Initial PSI: Tubing 6 Intermediate 23 Casing 50 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min		23	50		50	Steady Flow	
10 min		23	50		50	1 GAL Surges	X
15 min		23	50		50	Down to Nothing	
20 min		23	50		50	Nothing	✓
25 min		23	50		50	Gas	✓
30 min		23	50		50	Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 3

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND IT PRODUCED 4 GALLON OF WATER
IN THE FIRST 10 MINUTES AND LES THAN 1/2 A GALLON AFTER THAT.

REQUESTED A WATER ANALYSIS

By Jonathan Hardy
Senior Lease Operator
(Position)

Witness John Dorn

E-mail address _____