



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OR. CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://enrmd.state.nm.us/ocd/District/873/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test May 13 2014 Operator Lively Exp API #30-045-21074
Property Name Lively Well No. 3 Location: Unit N Section 29 Township 29N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 223 Intermediate 210 Casing 240 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
5 min	0	210	240		
10 min	0	210	240		
15 min	0	210	240		
20 min				0	240
25 min				0	240
30 min				0	240

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	X
Surges	
Down to Nothing	
Nothing	✓
Gas	X
Gas & Water	
Water	

OIL CONS. DIV DIST. 3

JUL 14 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 52

REMARKS: Intermediate Produced Gas for Test
(will have test)

By Russell Lane
Asst Lively Exp
(Position)

Witness _____

E-mail address _____