



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-4-14 Operator Burlington API #30-0 45-29936
Property Name Casaly & Sons Well No. 2 Location: Unit 22 Section 22 Township 30 Range 11
Well Status(Shut-In or Producing) Initial PSI: Tubing 887 Intermediate 0 Casing 6 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	6	0	6
10 min	0	0	6	0	6
15 min	0	0	6	0	6
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

DIST. 3

Surges

Down to Nothing

OIL CONS. DIV.

Nothing

Gas

RCVD HUG 4'14

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH Puff when opened

Int - Nothing when opened

By

Witness

(Position)

E-mail address

daniel.h.aguirre@ecp.com