



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-16-14 Operator Burlington Res API #30-0 45-26608
Property Name Pierce A Well No. 4E Location: Unit Section 13 Township 30 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 178 Intermediate 182 Casing 177 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	0	181	183	25	190
10 min	0	181	185	0	191
15 min	0	181	186	0	192
20 min				0	193
25 min				0	193
30 min				0	194

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	/
Surges	
Down to Nothing	/
Nothing	
Gas	/
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 1

REMARKS:

BH: Long puff dead at 4 seconds.
Int. Hand blow just 10 min - 15 light blow - 20 - 25 - 30

By Luis Coen
(Position)

Witness Monica Cuchling

E-mail address