



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/16/2014 Operator Merrion API # 30-045-31120

Property Name Chucky Well No. 3 Location: Unit A Section 23 Township 30 Range 12

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 7 Intermediate Casing 7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	—	9		
10 min	0	—	9		
15 min	0	—	9		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	RCVD SEP 16 '14
Surges	OIL CONS. DIV.
Down to Nothing	DIST. 3
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Just a whisper on bradenhead.

By Jim Merrill
Contract Pumper
(Position)

Witness Paul Wiehe

E-mail address