



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-19-07 Operator Patina San Juan, Inc. API # 3003906612

Property Name JICARILLA 4 Location: Unit E Section 8 Township 26 Range 5  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 47 Intermediate - Casing 58 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate Flowed Flowed	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>58</u>	<u>-</u>			Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	<u>-</u>
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear - Fresh - Salty - Sulfur - Black -

5 Minute Shut-in Bradenhead 0 Intermediate -

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Greg Vigil - [Signature]  
LEAD PUMPER  
(Position)

Witness \_\_\_\_\_

