



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-24-07 Operator Patina San Juan, Inc. API # 3003922509

Property Name NORTHWEST 3E Location: Unit L Section 6 Township 26 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing BI Intermediate — Casing 96 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>-0</u>	<u>96</u>	<u>—</u>				
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							
5 minute SI							

Steady Flow		
Surges		
Down to Nothing		
No Flow	<u>X</u>	<u>—</u>
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead 0 Intermediate —

REMARKS:

By Greg Vigil - [Signature] Witness _____
LEAD PUMPER
(Position)

