

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(Oubiiii	t z copies to at	ore addic	33,		
Date of Test	9-24-07 Operator			Patina San Juan, Inc.			API# 300	03923517
Property Name		HOYT 2E			Location: Unit I Section 5		ownship 26	Range 4
		(Well Name	and Number)					
Pressure (Shu	t-in or Proc	lucing	Tubing <u>s</u>	38_ Interme	diate	Casing <u></u>	8 Bradenh	nead <u>2</u>
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	PHERE IND	IVIDUALLY FOR	15 MINUTES E	ACH
	Bradenhead			Interme	diate		Bradenhead	Intermediate
<u>Time</u>	BH Biowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	-0	68				Steady Flow		
10 minutes		ريو				Surges		
15 minutes						Down to Nothing		
20 minutes		 				No Flow		
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		<u> </u>
If bradenher Clear 5 Minute Sh	F	resh _	Sal	escriptions than	t apply bel	Bla	REC POLICONS	D212223222 A RSP BENED REPORTED TO THE PROPERTY OF THE PROPERT
							8/99%	£ 2. V
By Gree	y Vigil	- 2	SUS	Wi	tness		····	
LEAG	Pum	PER						

(Position)