

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

			(Submi	t 2 copies to at	ove addre	35)			
Date of Test	9-18-07 Operator			Patina San Juan, Inc.			API# 30	3003923533	
Property Nam	e	HURON 4E			Location: Unit A Section 2		ownship 26	Range 4	
		(Well Name	and Number)						
Pressure (Sh	ut-in or Frod	lucing)	Tubing	48 Interme	diate	Casing 7	7 Bradeni	nead <u>O</u>	
OPEN	N BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	PHERE INC	DIVIDUALLY FOR	15 MINUTES I	EACH	
	Bradenhead			Interme	diate		Bradenhead Intermediate		
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes			Monitor	Biowdown	Worldor	Steady Flow			
10 minutes	<u>+</u>	77			<u> </u>	Surges			
15 minutes						Down to Nothing			
20 minutes						No Flow	<u> </u>		
25 minutes						Gas	•		
30 minutes						Gas and Water			
5 minute SI						Water	·		
Clear 5 Minute S REMARKS:	F	resh _	Sal	escriptions that	t apply bel	Bla	STAR 19202	0/5/1.3 CS	
		· · · · · · · · · · · · · · · · · · ·				, · · · · · · · · · · · · · · · ·	\$34E6		
By Gr Log	reg Vig 10 Pump		Ay Col) Wi	tness				
		(Positio	n)					•	