



**NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
http://www.emnrd.state.nm.us/ocd/

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 9-18-07 Operator Patina San Juan, Inc. API # 3003929259

Property Name MCINTYRE 1C Location: Unit E Section 11 Township 26 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 146 Intermediate - Casing 182 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water	Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor									
5 minutes	<u>0</u>	<u>182</u>	<u>-</u>						<u>X</u>					
10 minutes														
15 minutes														
20 minutes														
25 minutes														
30 minutes														
5 minute SI														

If bradenhead flowed water, check all of the descriptions that apply below:

Clear        Fresh        Salty        Sulfur        Black       

5 Minute Shut-in Bradenhead 0 Intermediate       

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



By Greg Vigil - Lead Pumper  
LEAD PUMPER  
(Position)

Witness \_\_\_\_\_